

# Firearm Barrel Break-in & Cleaning Process

Thanks to Team Member D.D., Victoria, BC, Canada

## **BREAK IN PROCESS**

Run Patchworm with 1 patch soaked with Prolix, both sides. Sit 10 min, Repeat if necessary.  
Run 2 super intensive felt cleaning buttons dipped in Prolix and smeared with J-B Bore Cleaner 9+ times each before first shot, reduce to 1 time each after first shot.  
Clean breech from bore cleaner with toothbrush and Prolix.  
Run 1 patch soaked with Prolix both sides.  
Run 2 plain felt button with J-B Bore Bright at leading edge 9+ times each before first shot, reduce to 1 time each after first shot.  
Clean breech from bore bright with toothbrush and Prolix.  
Run 1 patch soaked with Prolix, both sides. Repeat if necessary.  
First time and last time only: Soak all gun parts with Prolix for 20 minutes. Assemble and lubricate with one drop of Xtra-T Lube, each place in manual. Wipe outside of gun with silicone cloth.  
Before shooting run 3 dry patches, both sides, (not before storage).

Shoot 1, 2, 4, 8, 16, 32, 64, 128 rounds, each followed by above process except second last step, soaking.

To store at the end of the break in process: (Prolix snap cap for rim fires) touch up wipe outside of gun with Prolix and Xtra-T on a cloth, and store in silicone sock.

## **CLEANING PROCESS**

Before range/shooting: run Patchworm with 4 dry patches, each both sides.  
Bring to range: Patchworm and 4 patches soaked with Prolix.  
Immediately after range: run Patchworm with 4 patches soaked with Prolix, each both sides.

At Home:

Clean breech down to magazine, trigger linkage, and top of trigger with pipe cleaner and Prolix, or annually soak all parts.  
Run Patchworm with 1 patch soaked with Prolix, both sides.  
Run 1 super intensive felt button dipped in Prolix and smeared with J-B Bore Cleaner.  
Clean breech from bore cleaner with toothbrush and Prolix.  
Run 1 patch soaked with Prolix both sides. Repeat if necessary.  
Run 1 plain felt button dipped in Prolix and smeared with J-B Bore Bright.  
Clean breech from Bore Bright with toothbrush and Prolix.  
Run 1 patch soaked with Prolix, both sides. Repeat if necessary.

If soaked, lubricate with one drop of Xtra-T Lube each place in manual.

Store: (Prolix snap cap for rim fires), touch up wipe outside of gun with Prolix and Xtra-T on a cloth, and store in silicone sock.

Xtra-T Lube:

22A: 4 points on slide

Remington 870: None mentioned

Ruger 10/22: None mentioned

Glock: Slides, left top of slide, trigger to connector at right rear